



layers are joined together by a needling of about 20 - 70 stitches/cm<sup>2</sup>, preferably 20 - 50 stitches/cm<sup>2</sup>. A process for its manufacture is also described. The laminate is used for manufacturing polymer and bitumen webs, especially bituminised roofing felts and underfelts. <IMAGE>